ASSEMBLY INSTRUCTION

NC*FXX & NC*MXX | XLR Cable Connector

Ⓐ



Ⓑ



Ⓒ



Ⓓ



Ⓔ



Ⓕ



Ⓐ ***Slide the boot onto the cable.***

Ⓑ ***Prepare cable as shown.***

Ⓒ ***Insert wires into the terminals and solder them.***

Ⓓ ***Put chuck onto the cable.***
Attention: Pay attention to the guiding key.

Ⓔ ***Slide insert and chuck together into the housing.***

Ⓕ ***Finish the installation by turning the bushing onto the connector.***

ORDER OF ASSEMBLY

NC✶FXX



bushing | chuck | insert | housing

NC✶MXX

NEUTRIK AG	LI	T: +423 / 237 24 24	F: +423 / 232 53 93
NEUTRIK Zürich AG	CH	T: +41 44 / 736 5010	F: +41 44 / 736 5011
NEUTRIK USA Inc.	USA	T: +1 732 / 901 9488	F: +1 732 / 901 9608
NEUTRIK (UK) Ltd.	UK	T: +44 1983 / 811 441	F: +44 1983 / 811 439
NEUTRIK Vertriebs GmbH	DE / NL / AT	T: +49 8131 / 280 890	F: +49 8131 / 280 830
NEUTRIK France	FR	T: +33 1 / 4131 6750	F: +33 1 / 4131 0511
NEUTRIK Tokyo Ltd.	JP	T: +81 3 / 3663 4733	F: +81 3 / 3663 4796
NEUTRIK Hong Kong Ltd.	HK	T: +852 / 2687 6055	F: +852 / 2687 6052

Draft. Nr.: BDA 158 / 3102M1381 | Update: 12..03.2008 |

Data subject to change without prior notice. ©2008NEUTRIK® . ALL RIGHTS RESERVED.

www.neutrik.com

NEUTRIK