




ASSEMBLY INSTRUCTION

NC3FXX-14 & NC3MXX-14 | XLR Cable Connector



A Slide the boot onto the cable.

B Prepare cable as shown.

C Insert wires into the terminals and solder them.

D Put chuck onto the cable.

Attention:

(1) Pay attention to the guiding key.

(2) Align the slot of the chuck to the spring.

E Slide insert and chuck together into the housing.


F Finish the installation by turning the bushing onto the connector.

OPTION:

Use the handtool HTXX-14 to tighten the bushing.

ORDER OF ASSEMBLY

NC*FXX




bushing



chuck




insert



housing

NC*MXX



Find more details of XLR Connectors on
www.neutrik.com.

NEUTRIK AG LI T: +423/237 24 24 F: +423/232 53 93
NEUTRIK USA Inc. USA T: +1 704/972 3050 F: +1 704/438 9202
NEUTRIK (UK) Ltd. UK T: +44 1983/811 441 F: +44 1983/811 439
NEUTRIK Vertriebs GmbH DE/NL/AT/DK T: +49 8131/280 890 F: +49 8131/280 830

NEUTRIK France FR T: +33 1/4131 6750 F: +33 1/4131 0511
NEUTRIK Tokyo Ltd. JP T: +81 3/3663 4733 F: +81 3/3663 4796
NEUTRIK Hong Kong Ltd. HK T: +852/2687 6055 F: +852/2687 6052
NEUTRIK India Pvt. Ltd. IND T: +91/982 05 43 424 F: +91/22 26163 540

Draft. Nr.: BDA 198 | Update: 02.06.2016 | Data subject to change without prior notice. ©2016 NEUTRIK®. ALL RIGHTS RESERVED. NEUTRIK® are registered trademark.

www.neutrik.com

NEUTRIK