
Riedel Headset Wiring Guide

Pinout from the headset side



Pinout from the gear side



Pin	Headset A	Headset B
1	HS MIC A - , (GND)	HS MIC B - , (GND)
2	HS MIC A + , (+5 VDC)	HS MIC B + , (+5 VDC)
3	GND	GND
4	HS Phones A + (left)	HS Phones B + (left)

figure 92: Headset connector XLR-4 male pinout