



ASSEMBLY INSTRUCTION


NADB9/15* | D-Sub Adapter

Screws

D-Sub connector
front plate

Equipment / Panel

D-Sub



- A** Insert D-Sub adapter from the rear as shown.
- B** Position the connector front plate and
- C** screw on.

NEUTRIK AG
NEUTRIK USA Inc.
NEUTRIK (UK) Ltd.
NEUTRIK Vertriebs GmbH
NEUTRIK France
NEUTRIK Tokyo Ltd.
NEUTRIK Hong Kong Ltd.
NEUTRIK India Pvt. Ltd.

LI
USA
UK
DE/NL/AT/DK
FR
JP
HK
IND

T: +423/237 24 24	F: +423/232 53 93
T: +1 704/972 3050	F: +1 704/438 9202
T: +44 1983/811 441	F: +44 1983/811 439
T: +49 8131/280 890	F: +49 8131/280 830
T: +33 1/4131 6750	F: +33 1/4131 0511
T: +81 3/3663 4733	F: +81 3/3663 4796
T: +852/2687 6055	F: +852/2687 6052
T: +91/982 05 43 424	F: +91/22 26163 540



Draft. Nr.: BDA 382 | Update: 22.08.2014 | Data subject to change without prior notice. ©2014 NEUTRIK®, ALL RIGHTS RESERVED. NEUTRIK® are registered trademark.

www.neutrik.com

NEUTRIK®