




# ASSEMBLY INSTRUCTION

## NC3FFX-14 & NC3MXX-14 | XLR Cable Connector



- A** Slide the boot onto the cable.
- B** Prepare cable as shown.
- C** Insert wires into the terminals and solder them.
- D** Put chuck onto the cable.  
**Attention:**  
(1) Pay attention to the guiding key.  
(2) Align the slot of the chuck to the spring.
- E** Slide insert and chuck together into the housing.
- F** Finish the installation by turning the bushing onto the connector.

**OPTION:**  
Use the handtool HTXX-14 to tighten the bushing.

**ORDER OF ASSEMBLY**

<b>NC* FXX</b>			
bushing	chuck	insert	housing
<b>NC* MXX</b>			



Find more details of XLR Connectors on [www.neutrik.com](http://www.neutrik.com).

NEUTRIK AG	LI	T: +423/237 24 24	F: +423/232 53 93	NEUTRIK France	FR	T: +33 1/4131 6750	F: +33 1/4131 0511
NEUTRIK USA Inc.	USA	T: +1 704/972 3050	F: +1 704/438 9202	NEUTRIK Tokyo Ltd.	JP	T: +81 3/3663 4733	F: +81 3/3663 4796
NEUTRIK (UK) Ltd.	UK	T: +44 1983/811 441	F: +44 1983/811 439	NEUTRIK Hong Kong Ltd.	HK	T: +852/2687 6055	F: +852/2687 6052
NEUTRIK Vertriebs GmbH	DE/NL/AT/DK	T: +49 8131/280 890	F: +49 8131/280 830	NEUTRIK India Pvt. Ltd.	IND	T: +91/982 05 43 424	F: +91/22 26163 540

Draft. Nr.: BDA 198 | Update: 02.06.2016 | Data subject to change without prior notice. ©2016 NEUTRIK®. ALL RIGHTS RESERVED. NEUTRIK® are registered trademark.

[www.neutrik.com](http://www.neutrik.com)

**NEUTRIK®**