




ASSEMBLY INSTRUCTION

NP2RX-ULTIMATE | 1/4" Guitar - ultimatePLUG


A



Slide the boot onto the cable.

B

Cable O.D. 4.0 - 7.0 mm [0.16 - 0.27"]




Prepare cable as shown.

C

TIMBRE

Tip
Shield
Silent Switch




Position the red cover next to the shell:

① Solder the SHIELD to the ground lug.

② Solder the red cable (TIMBRE) combined with the hot wire to the TIP lug.

E




Sliding the screw (D) into the hole and between the wires before

Position the cover on the shell (E) and fix it with a screw driver (POZIDRIV® #1) the screw (F).


F






Position the chuck on to the cable and move it into the housing.

Attention: Pay attention to the guiding key of the chuck.



Finish the installation by tighten the bushing onto the connector.



FINISH

NEUTRIK AG
NEUTRIK USA Inc.
NEUTRIK (UK) Ltd.
NEUTRIK Vertriebs GmbH

LI
USA
UK
DE/NL/AT/DK

T: +423 / 237 24 24
T: +1 704 / 972 3050
T: +44 1983 / 811 441
T: +49 8131 / 280 890

F: +423/232 53 93
F: +1 704/438 9202
F: +44 1983/811 439
F: +49 8131/280 830

NEUTRIK France
NEUTRIK Tokyo Ltd.
NEUTRIK Hong Kong Ltd.
NEUTRIK India Pvt. Ltd.

FR
JP
HK
IND

T: +33 1/4131 6750
T: +81 3/3663 4733
T: +852/2687 6055
T: +91/982 05 43 424

F: +33 1/4131 0511
F: +81 3/3663 4796
F: +852/2687 6052
F: +91/22 26163 540