







# ASSEMBLY INSTRUCTION


## NC\*FXX & NC\*MXX | XLR Cable Connector


**(A)** 

**(B)** 

**(C)** 

**(D)** 

**(E)** 

**(F)** 

**(A)** Slide the boot onto the cable.

**(B)** Prepare cable as shown.

**(C)** Insert wires into the terminals and solder them.





**(D)** Put chuck onto the cable.  
**Attention: Pay attention to the guiding key.**

**(E)** Slide insert and chuck together into the housing.





**(F)** Finish the installation by turning the bushing onto the connector.

**ORDER OF ASSEMBLY**

**NC\*FXX**

			
bushing	chuck	insert	housing

**NC\*MXX**

			
--	---	---	---

<p>NEUTRIK AG NEUTRIK Zürich AG NEUTRIK USA Inc. NEUTRIK (UK) Ltd.</p>	<p>LI CH USA UK</p>	<p>T: +423 / 237 24 24 F: +423 / 232 53 93 T: +41 44 / 736 5010 F: +41 44 / 736 5011 T: +1 732 / 901 9488 F: +1 732 / 901 9608 T: +44 1983 / 811 441 F: +44 1983 / 811 439</p>	<p>NEUTRIK Vertriebs GmbH DE/NL/AT NEUTRIK France FR NEUTRIK Tokyo Ltd. JP NEUTRIK Hong Kong Ltd. HK</p>	<p>T: +49 8131 / 280 890 F: +49 8131 / 280 830 T: +33 1 / 4131 6750 F: +33 1 / 4131 0511 T: +81 3 / 3663 4733 F: +81 3 / 3663 4796 T: +852 / 2687 6055 F: +852 / 2687 6052</p>
--	---------------------------------	--	--	--

Draft. Nr.: BDA 158 / 3102M1381 | Update: 12..03.2008 | Data subject to change without prior notice. ©2008NEUTRIK®. ALL RIGHTS RESERVED.